

(Isuzu models supported to : NRP300,NRP500, Canter,NR400, NNR200, EFI, Dmax, Truck)

- Adblue VAG EDC17CP24 has been improved
- Adblue - DAF PC3 has been improved for new models.
- Adblue EDC17CP20 improved for Passat models.
- Adblue EDC17CP20 more improved
- Alfa EDC16C39 Solution 2 improved for some file types.
- Audi - VW EDC17CP04 improved for new models.
- Audi - VW EDC16U31 4x switch type file signs added
- Audi - VW EDC16U31 Switch solution added
- Audi - VW EDC16U34 P0545 and P0546 DTC automatic removing added
- Audi - VW EDC17C46 signs more improved
- Audi - VW EDC17C46 signs more improved
- Audi - VW EDC17CP04 Flap removing added
- Audi - VW EDC17CP04 solution has been improved
- Audi - VW EDC17CP20 Flap solution has been added
- Audi EDC16CP34-4 revized fixed.
- Audi EDC16CP34-4 solution revised with new.
- Audi EDC17CP04 2th switch added
- Audi EDC17CP14 has improved for support to Q5 models.
- Audi EDC17CP44 switch fixed for Audi car.
- Audi EDC17CP54 added
- Audi PCR2.1 regeneration switch alternate added
- Audi PPD1.x new solution added
- BMW 1mb Type1 solution added 525 models.
- BMW EDC16C35 supported to all types (Generic)
- BMW EDC16C35-2 item added DDE7 support
- BMW EDC17C41 added
- BMW EDC17C56 solution added
- BMW EDC17CP06 DTC Root + DTCx80 removing added
- BMW EDC17CP45 ASC solution added
- BMW Mini EDC15C35 bug fixed.
- Chevrolet DCM3.7 improved, DTC structure fixed
- Chevrolet Delphi DCM3.7 acceleration problem fixed
- Chevrolet EDC16C39 added
- Chevrolet EDC16C39 has been improved
- Chevrolet EDC16C39 improved
- Chrysler EDC16C31 added alternate solution
- Chrysler EDC16CP31 solution improved
- Citroen - Peugeot EDC17C10 added more DTCs
- Citroen - Peugeot EDC17C10 Additive Pump removing improved
- Citroen Berlingo EDC17C10 added
- Citroen Delphi DCM3.5 Type2 added in main solution
- Citroen EDC17C10 solution Picasso model support added
- Citroen SID803A supported with Peugeot SID803A solution now
- Citroen SID807 EGR + DPF added
- Citroen SID807 sign are improved
- Dacia Delphi DCM3.4 solution has been added
- Dacia Delphi DCM3.4 solution has been added.
- Dacia section added with EDC17CP42 ECU.
- Denso map8 problem fixed
- Dodge EDC16U31 solution has been added
- EDC17CP02 - CP06 New DTC's added
- EDC17CP14 Flap removing has been improved for different models.
- EDC17CP14 solution improved
- EDC17CP24 bug fixed Tamarrov
- Fiat 6F3 Generic added Fiat500 models
- Fiat 8F2 signs are improved,
- Fiat 8F3 solution fixed
- Fiat 8F3 solution Improved
- Fiat 8F3 solution Improved

- Fiat Doblo 6Fx improved for other models
- Fiat Ducato type more improved
- Fiat EDC16C39 Generic improved for Chrome models.
- Fiat Grande Punto 8F2 improved to other models
- Fiat Marelli 6F3 solution automatic EGR disable function removed.
- Fiat Marelli 8F3 Generic P1564 DTC removing has been added
- Fiat Marelli 8F3 solution added
- File control : CMD, Kess formats and blank file controlling added.
- Fixed 62 signs problems reported by customers.
- Fixed some Flap items was showing DPF removing message.
- Flap EDC16C34 EDC16CP34 revised
- Flap EDC16U1 Golf5 new sign added
- Flap EDC17CP14 Audi different type sign added
- Flap EDC17CP14 Audi different type sign added
- Ford 9M51 type solution item added
- Ford DCM3.5 Type2 solution(983kb) has been improved for Mondeo models
- Ford Connect Solution new DTCs added for removing
- Ford Delphi DCM3.2 solution has been added.
- Ford Delphi DCM3.5 Improved for other models.
- Ford Delphi DCM35 P2463 and P246b DTC removing added
- Ford EDC16C3.9.18 added
- Ford EDC16C34 Additive removing added
- Ford EDC16C34 improved for Cmax models
- Ford EDC16C34 switch P2484 2th DTC added
- Ford EDC17C10 solution has been added
- Ford Focus EDC16C34 Switch solution new signs added
- Ford Mondeo Delphi DCM3.5 type ECU solution added
- Ford Sid206 Generic improved for Mondeo model
- Ford SID206 Generic solution improved for modified files.
- Ford SID206 Kuga renew solution tested with
- Ford SID208 EGR + DPF added
- Ford SID208 P244D DTC removing added
- Ford SID208 Transit and Ranger models supports improved
- Ford SID803A new solution added
- Ford Transit Connect Type solution added new DTCs
- Ford Transit Connect Type solution added new DTCs
- Ford, Citroen, Peugeot, Volvo EDC16C34 switch solution
- Generic EDC16 - EDC17 Switch search improved with new add switch solutions
- Golf5 EDC16U1 Flap added
- Honda Civic solution improved for different ECU soft versions.
- Honda EDC16C31 solution improved
- Honda EDC17CP06 has been improved
- Honda EDC17CP16 switch solution added
- Honda EDC17CP16 switch solution added
- Hyundai - KIA EDC16C39 Switch solution added
- Hyundai / KIA EDC17C08 Double DPF switch problem fixed
- Hyundai EDC16C39 Generic improved for Tucson models.
- Hyundai Generic Switch solution new DTC's added
- Hyundai SantaFe solution added
- In Toyota Denso solution added Prado VX model support.
- Isuzu Transtron NR400 Model EGR + DPF support added
- Isuzu Transtron Dmax added
- Isuzu Transtron EFI, Canter, NLP models solution added
- Isuzu Transtron improved for Dmax Type2 models.
- Isuzu Transtron NNR200 model support added
- Isuzu Transtron P2002 P0401 automatic DTC removing has been added
- Italian language text has been revised
- Italian Language totally revised, now more good
- Iveco EDC17CP52 more DTCs removing has been added
- Iveco EDC17CP52 solution added (EGR + DPF)
- Jaguar EDC17CP11 added
- Jaguar EDC17CP11 fixed some DTC's
- Jaguar SID204 fixed, improved for added models.
- Jaguar SID204 reported P0000 problem fixed

- Jaguar SID204 solution has been improved
- Jeep and Dodge EDC17C79 switch solution has been added
- Jeep EDC16CP31 DTC removing improved.
- Jeep EDC16U1 added new automatic switch solution
- Jeep EDC16U1 added new automatic switch solution
- Jeep EDC17C79 added
- Jeep Grand Cherokee EDC16CP31 added
- KIA Carens 5th search point fixed
- KIA EDC17C08 solution has been improved.
- KIA EDC17C08 Switch added
- Lancia 6f3 Solution added
- Lancia 8F3 solution improved
- Lancia EDC16C39 added
- LandRover Sid208 added
- M55 solution improved for lmb files.
- Mazda 3 Denso models P2584 P2585 DTC removing added
- Mazda CX7 Adblue + DPF more improved
- Mazda CX7 Adblue remove added
- Mazda Denso Partial DTC added
- Mazda EDC16C34 revised.
- Mazda EDC16C34 Switch solution added
- MB EDC16C31 2011+ solusyon improved for MB Vivano models.
- MB EDC17C10 Switch added, DTC's improved
- MB Flap M55 improved.
- Mercedes EDC17C01 - CP01 switch solution has been added
- Mercedes 2011+ solution restored again.
- Mercedes DCM3.5 4MB Type2 solution added
- Mercedes DCM3.5 solution DTC P244A added
- Mercedes DCM3.5 Type1 solution improved, added new DTC's.
- Mercedes DCM3.5 Type2 DTC section totally revized
- Mercedes DCM35 CRD Type2 4MB P2454 DTC removing added
- Mercedes Delphi DCM3.5 CRD2 Type1 solution added P2279 automatic removing
- Mercedes Delphi DCM35 Type1 P0475 automatic removing added
- Mercedes EDC16C31 - CP31 item improved for MB CLS Models
- Mercedes EDC16C31 lmb Type1 solution improved for W211 models
- Mercedes EDC16C31 Type2 Generic solution improved
- Mercedes EDC16CP31 solution improved for ML models
- Mercedes EDC16CP31 solution improved for ML models
- Mercedes EDC16CP36 solution revized
- Mercedes EDC16CP36 Type1 solution 2 new signs added
- Mercedes EDC17CP10 solution improved.
- Mercedes EDC17CP10 solution revized
- Mercedes EDC17CP46 solution improved
- Mercedes ML EDC16C31 support has been improved
- Mercedes Sprinter EDC17CP46 switch solution added
- Mercedes Sprinter EDC17CP46 switch solution added
- Mitsubishi Denso 2th solution added for compatible other some models.
- Mitsubishi Denso has been improved
- Mitsubishi EDC16CP39 Switch solution has been added
- Mitsubishi EDC17CP15 DPF + EGR solution has been added
- Mitsubishi EDC17CP15 has been improved
- Nissan EDC16CP33 Type2 solution has been improved for more new models.
- Nissan EDC17C42 opening problem has been fixed
- Nissan SID305 P1525 fixed, improved
- Opel - Vauxhall OpelEDC17C59 Switch solution added
- Opel EDC17C59 improved.
- Opel Astra J special solution added
- Opel Astra J special solution added
- Opel Denso Partial DTC solution improved
- Opel Denso solution improved for DTC, light problems
- Opel EDC16C39 Antara added in main solution.
- Opel EDC16C9 EGR + DPF 1x P1901 DTC fixed.
- Opel EDC16C9 EGR + DPF 1x P1901 DTC fixed.
- Opel EDC17C18 - 19 revized

- Opel EDC17C18 Corsa D files signs has been added.
- Opel EDC17C18 improved
- Opel EDC17C18 some DTC problems fixed
- Opel EDC17C18-19 solution improved
- Opel EDC17C18-19 solution improved for Vauxhall EDC17 ECUs
- Opel EDC17C42 added from Nissan and Reanult solutions
- Opel Marelli 75-90CV solution added new file type sign
- Opel Z13DTJ improved
- PCR2.1 solution added new DTCs
- PCR2.1 solution added new DTCs
- PCR2.1 solution improved for Golf 1.6TDI models.
- Peugeot EDC16C34 solution improved for some models.
- Peugeot DCM3.4 added in Citroen section
- Peugeot DCM3.4 solution improved.
- Peugeot DCM3.5 solution improved for other models.
- Peugeot EDC15C2 different type signs added
- Peugeot EDC15C2 some DTCs removing added
- Peugeot EDC16C34 P2033 and P1461 DTC removing added
- Peugeot EDC17C10 disable more DTC's about DPF additive system
- Peugeot SID803 MPC solution has been improved.
- Peugeot SID803A Generic improved.
- Peugeot SID803A Generic item improved for Peugeot Expert2.0 models
- Peugeot SID803A Generic solution improved
- Peugeot SID803A Type new signs added
- Peugeot DCM3.4 improved for more compatible
- Peugeot SID803A generic added Boxer model signs
- Peugeot SID803A generic added Boxer model signs
- PPDv1.x revized with new solution.
- Protections improved, lots of trap points added.
- PSA Delphi DCM3.5 added
- PSA EDC15C2 bug fixed
- PSA EDC16C0-7, EDC167C0-9 improved
- PSA EDC17C09 - 10 bug fixed
- PSA Group EDC15C2 Aditiv + Flap removing added
- PSA SID803 MPC more improved
- PSA SID807 item normal and EVO integration has been completed.
- Range Rover EDC17CP11 added, improved.
- Renault (Laguna) EDC16C3 solution revized
- Renault and Nissan EDC17C42 solution added
- Renault and Nissan EDC17C42 solution added
- Renault DCM3.4 New DTCs automatic removing has been added
- Renault Delphi DCM3.4 solution improved with new DTCs
- Renault Delphi DCM34 solution has been improved
- Renault EDC16C3 Type1 and Type2 DTC's optimized
- Renault EDC16CP33 sign are improved.
- Renault EDC16CP36 improved
- Renault EDC17C11 Switch added, improved
- Renault EDC17C42 improved
- Renault EDC17C42 new automatic DTCs added.
- Renault EDC17C42 P0294 DTC automatic removing added
- Renault EDC17C42, Saab EDC16C39 solution signs are improved.
- Renault SID305 new sign added
- Renault SID305 P1525 and P2002 extra DTC removing codes added
- Renault SID305 solution added
- Renault SID305 solution improved for Laguna models.
- Renault Type2 improved
- Saab EDC16C39 bug fixed
- Seat EDC17U01 Ibiza model ECU extra DTCs added
- SID206 Generic added Galaxy model points
- SID305 Nissan and Megane added
- SID803 MPC DTC0000 problem has been fixed.
- Siemens PPD1.x Flap removing has been added
- Siemens PPD1x ECU's added New optimized solution
- Skoda EDC17U01 switch solution added

- Skoda SuperB EDC16U31 added
- Subaru Denso added
- Subaru Denso DTC calculation bug has been fixed
- Suzuki DDIS optimized
- Suzuki EDC16C39 solution improved
- Suzuki EDC16C39 solution improved for other models.
- Suzuki EDC16C8-10 solution has been improved.
- Swedish Language has been added
- Toyota Denso solution has been improved
- Toyota Denso solution improved
- Toyota EDC17CP07 improved for Yaris, Auris models
- Toyoto Denso P2031 DTC added
- Toyoto Denso P2031 DTC added
- Treeview font 1 punto decreised.
- Update EDC16-17 fast search section.
- Vauxhall - Opel EDC17C59 solution improved
- Volvo SID803 MPC DTC removing has been optimized for DPF relate only
- Volvo EDC16C31 Switch solution DTC area optimized
- Volvo EDC16C31 solution DTC removing has been improved
- Volvo EDC16C34 Additive Control and Liquid DPF automatic removing added
- Volvo EDC17CP22 + EGR + DTCs added
- Volvo SID803 MPC solution improved
- Volvo SID803A Revized
- VAG EDC17C64 solution improved for other models.
- VAG DCM37 solution DTC bug has been fixed.
- VW - Porsche EDC17CP44 added
- VW Amarok EDC17CP52 switch solution aded
- VW Audi Q7 EDC17CP24 Switch added and improved for other models
- VW Crafter added new signs for supporting to different soft versions.
- VW EDC16C46 Passat Models P246e DTC automatic added
- VW EDC17C64 switch solution has been added
- VW EDC17CP14 solution improved for Golf6 models
- VW EDC17CP14 Swirl Flap solution added
- VW EDC17CP24 DPF Switch sign revized
- VW EDC17CP46 DTC Root + DTCx80 removing added
- VW EDC17CP52 menu bug fixed
- VW EDC17CP54 Switch solution added
- VW Group EDC17C46 new DTCs added

Alfa : EDC16C39 Type1 and Type2
Audi : EDC16UX,EDC16CP3 / 34, EDC16U31, EDC17CP14, Siemens PPD
v1.1, V1.2, V1.3,
EDC17CP44,EDC17C46,EDC17CP04, EDC16C34-4
BMW : EDC16C31 - 35, EDC16C31 (1MB), EDC17CP02,EDC16CP35,
EDC16C31New, EDC16C35,EDC17CP45
EDC17C41

Chrysler : EDC16CP31
Chevrolet : EDC16C39
Citroen : EDC15C2, EDC16C34, EDC17C10, SID807
Fiat : EDC16C39(Ducato), EDC16C39 JTD, MJD 6F3, 6F3 Doblo, EDC16C39
Generic, SID803A,
Marelli 8F2, Marelli 8F3,
Ford : EDC16C34,EDC16C34-2, EDC16C34-2.29, EDC16C34-5, SID 206,
SID807, SID803MPC,
SID803A, SID206(SMAX type), SID206 Kuga, EDC16C34 Picasso
Type, EDC16C3-9.18
Lancia : EDC16C39
Honda : EDC16C31, EDC17CP06, EDC16C31(Advanced)
Hyundai / KIA : EDC16C39-D373, KIA EDC16C39 Type2, Hyundai EDC16C39 Caren,
EDC16C39 SantaFE, EDC17C08
Iveco : EDC16C39
Isuzu : Denso, Transtron DMax
Jaguar : SID204, EDC17CP11

Jeep : EDC16U1, EDC16CP31, EDC17C49
 LandRover : EDC16C39-Ford, SID208
 Mazda : Denso 3-8 all series, EDC16C3, Denso CX7 Type with Adblue,
 EDC16C34
 Mercedes : EDC16C31, Delphi DCM3.4, EDC16C31 Vito and Type2, EDC16CP36,
 EDC16C3, EDC16C31(2011+)
 EDC17CP10, M55 Error fixer
 Mini Cooper : EDC16C35
 Mitsubishi : Denso (Full 2 types supported), EDC16CP39
 Nissan : Denso, EDC16C36, EDC16CP33 Type1 and Type2, SID305
 Opel-Vauxhall : Denso, Denso Signum, EDC16C39, EDC16C9, EDC17C18 - C19,
 Marelli MJET 75-90cv, Z16DT Marelli,
 Denso Signum, Z16DTC, Z19DT
 Peugeot : EDC16C34, EDC15C2, SID803 MPC, Delphi DCM3.5, SID803A, Delphi
 DCM3.4
 Porsche : EDC17CP44
 Range Rover : EDC17CP11
 Renault : EDC16C3 Type1 and Type2, EDC16C32, SID305, EDC16C11
 Saab : EDC16C39, EDC16C9
 Skoda : EDC17CP14, PCR2.1, Octavia19
 Bosch, EDC17U01, EDC17CP20, EDC16CP44, EDC17U01
 Seat : Siemens PPD V1.2, PCR 2.1,, EDC17U01, EDC17CP20, EDC16CP44
 Subaru : Denso
 Suzuki : EDC16C3 Type1 and Type2, EDC16C39
 Toyota : EDC17CP07
 Volvo : EDC16C31 Type1 and Type2, SID803MPC, EDC16C34, SID803A Type1
 and Type2, EDC17CP22
 VW : EDC16CP34, EDC16U31,, EDC17CP14, PCR2.1, EDC16CP34-4,
 EDC17U01, EDC17CP20, EDC16CP44
 EDC17CP46, EDC17CP52, EDC17P24, EDC17CP44, EDC17CP54

 All : EDC16 - EDC17 ECU's automatic DPF switch finder item

 * : Some EDC16 and all EDC17 ECU's solutions are using internal
 switches.

 Flap support list:

Audi a4, a6 EDC16CP34
 Toureg EDC16CP34-4
 Jeep EDC16CP31
 Audi EDC16C34 Alternate
 Audi V6TDI 3.0
 Vectra C EDC
 EDC15VM P0098 (In EGR Remover)
 EDC16U1 Flap Solution
 EDC17CP04
 EDC17CP14

 Professional EGR Remover v2017.05.1

- Added these custom DTC removers :
- Citroen - Peugeot EDC17C10
 - Audi VW MED17.1
 - Mercedes EDC17CP46
 - Toyota EDC17CP07 - CP37
 - Hyundai - KIA EDC16C39
 - BMW EDC17CP45
 - Mitsubishi EDC17CP15

- BMW EDC17CP35
 - Fiat Marelli 8F3
 - BMW EDC18CP09
 - VAG EDC16C34
 - Fiat EDC16C39
 - Ford EDC17C10
 - Iveco EDC17CP52
 - Toyota EDC16C31
 - EDC17CP04
 - EDC17CP14
 - EDC17CP20
 - EDC17CP46
 - EDC17C64
 - MB EDC17CP10
 - BMW EDC17CP02
 - Alfa EDC16C8
 - Honda EDC17CP06
 - Renault Nissan SID305
 - Peugeot - Citroen EDC16C34
 - Fiat, Alfa ,Chevrolet EDC15C7
 - PSA Group SID803a
 - Ford SID803
 - Ford SID803a
 - Ford SID206
 - PPDv1.x
 - Mercedes EDC16C31
 - VW EDC16U1 series
 - EDC17CP14 custom DTC Removing internal BETA (next update will be added)
 - Still in progress : Delphi DCM3.5, DCM3.7 EGR, Opel Denso, (in development, tested)
 - Ford EDC16C34.2.30 total DTC
 - Alfa EDC16C39 total DTC
 - Audi EDC17C14 P2014 (Flap)
 - VM EDC15CVM P0098 (Flap)
 - Mercedes EDC16C31 DTC full table erase
 - Immo Generic EDC17 Solution.
-
- 103 alternate signs added, increising file supporting
 - Alfa EDC16C39 Generic has been improved for other models.
 - Alfa EDC16C39 generic solution improved more
 - Alfa EDC16C39 generic solution improved more
 - Alfa EDC16C39 Solution1 added more sings for Alfa - Fiat - Lancai models
 - Alfa EDC16C8 has been more improved
 - Alfa EDC16C8 P0401 DTC automatic removing has been added
 - Alfa EDC17C49 EGR + DPF added
 - Alfa Guilette EDC16C39 special solution added in Typel item
 - Audi - Skoda EDC15P solution added
 - Audi - VW EDC16U31 Generic revized, EDC16U34 ignored.
 - Audi - VW EDC17C46 solution improved with new DTCs
 - Audi - VW EDC17C46 Type4 solution added.
 - Audi - VW Marelli 4MV added Golf4 models supports.
 - Audi - VW ME7.5.10 solution improved and added on Audi cars support
 - Audi - VW PCR2.1 generic added new DTCs
 - Audi - VW PCR2.1 generic item support problems has been solved.
 - Audi A3 models EDC17C46 EGR hysteresis map problems has been fixed.
 - Audi EDC15VM+ solution now generic
 - Audi EDC16U31 Typel solution revized
 - Audi EDC17CP14 Type2 solution added
 - BMW EDC15 Switch solution added
 - BMW EDC16C31 solution improved.
 - BMW EDC17C06 improved
 - BMW EDC16C31 custom DTC calculation bug fixed.
 - BMW EDC17C06 solution improved with new DTC removing
 - BMW EDC17CP02 added

- BMW EDC17CP02 and EDC17C06 supported now, DTC's has been added
- BMW EDC17CP02 EDC17CP06 solution problems are fixed.
- BMW EDC17CP02 solution has been improved.
- BMW EDC17CP06 improved
- BMW EDC17CP06 revised.
- BMW Mini EDC16 solution revized
- Chrysler EDC15 EGR switch solution added
- Chrysler EDC15 EGR switch solution added
- Citroen - Peugeot EDC16CP39 added RuiSouza
- Citroen - Peugeot SID803a Type2 new DTC's added.
- Citroen - Peugeot EDC16C34 EGR removing solution seperated
- Citroen EDC15C3 3 new DTCs added.
- Citroen EDC16C34 Berlingo signs added
- Citroen EDC17C10 solution added
- Citroen SID803A type custom DTC added in SID803 item
- Custom DTC removing EDC17C46 Tiguan ECUs supports has been added.
- EDC16U1 new type added, bug fixed.
- EDC16U34 Generic Switch added, improved
- EDC16U34 has been improved for other models.
- EDC17 Immo section improved for other EDC17 ECU's
- EDC17C46 - CP46 bug has been fixed.
- EDC17C46 fixed for Passat and Alhambra models.
- EDC17C46 Type overflow fixed.
- EDC17CP04 solution improved
- EDC17CP14 custom DTC removing improved for other models.
- EDC17CP14 Solution1 P0401 DTC disabled added.
- EDC17CP24 DPF signs conflict fixed
- Fiat 8F3 improved for specially Ducato models
- Fiat 8F3 solution P0409 and P0486 removing added
- Fiat Bravo model added in Fiat Generic EDC16c39 item
- Fiat Doblo solution improved
- Fiat ducato type added
- Fiat Marelli 8F2 and 8F3 EGR solution added
- Fiat Marelli 8F3 solution added generic P0486, P0488,P0489 and P0409 DTC removing
- Fiat SID803A added new DTCs for removing automatical
- Fiat SID803A file id check has been removed, solution improved
- Fiat,Alfa,Opel, Lancia, Citroen, Ducato,Hyundai,KIA,Saab EDC16C39 generic switch solution added
- File control : CMD, Kess formats and blank file controlling added.
- Flap EDC16C34 Generic improved for EDC16C34 softwares
- Flap EDC16U31 P3103 added
- Flap EDC16U34 solution2 DTC calculation added
- Flap EDC17CP04 added
- Flap EDC17CP14 some models bug fixed (
- Ford DCM3.5 improved for other models.
- Ford Delphi DCM3.5 solution optimized, revised
- Ford EDC16C34 Additive removing added
- Ford EDC16C34 Focus models bug has been fixed
- Ford EDC16C34 M.Patil Type ECU software solution has been added
- Ford EDC16C34 signs are improved for different soft versions
- Ford EDC16C34 some version support fixed
- Ford EDC16C34 Switch solution added U0118 DTC disabled
- Ford Sid 202 EGR Hyst. added
- Ford SID202 P0489 DTC removing added
- Ford SID204 added new DTC points
- Ford SID206 Generic solution improved for other models.
- Ford SID206 P0490 added
- Ford SID206 P141a DTC conflict has been fixed.
- Ford SID206 P246x DTCs added
- Ford SID206 revized
- Ford SID206 Type DTC's improved
- Ford SID206 Type EGR Hystresis map problem solved.
- Ford SID208 different size maps added

- Ford SID208 has been improved
- Ford SID208 improved
- Ford SID208 more DTCs added
- Ford SID208 optimized for Ranger and Transit model.
- Ford Sid802 solusyon improved
- Ford SID802 solution improved
- Ford SID803 new 2 solusyon added
- Ford SID803 P0490 disabled added
- Ford SID803 P1412 DTC removing added
- Ford SID803A added new DTCs
- Ford SID803A optimized for Cmax model
- Ford SID803A P2002 DTC removed problem fixed
- Ford SID804 Type2 Solution added
- Ford TDCI Delphi DCM32 Micro EGR removing solution has been added.
- Ford Visteon 256kb type added
- Ford Visteon DCU102 improved
- Ford Visteon revized for also Peugeot
- Hotstart Golf5 Type added new signs for different type maps
- Hyundai / KIA solution totally revised.
- Hyundai EDC15c7 added
- Hyundai EDC16C39 Generic item added full KIA support
- Improved dongle protection, added more data in dongle.
- In Hyundai EDC16C39 switch solution important bug fixed
- In PCR2.1 P246E DTC removing added.
- Isuzu DMax Added (Aldo)
- Isuzu Dmax improved with new file types
- Italian language text has been revised
- Italian Language totally revised, now more good
- Iveco EDC16C39 EGR related DTCs automatic removing has been added
- Iveco EDC16C39 revized
- Jaguar Delphi DCM3.2 solution added
- Jaguar SID204 solution added
- Lancia 8F3 EGR removed added
- Land Rover SID204 added
- Land Rover SID204 bug fixed
- Land Rover SID204 solution
- Land Rover Visteon DCU solution added
- Marelli IAW4MV solution has been added
- Mazda Denso solution add signs for Mazda6 models.
- Mazda EDC16C3-9 DTC's Improved
- MB EDC15C6 Switch ve EGR MAP added
- MB EDC16C31 1MB Type1 solution added new signs.
- MB Vito solution added new sign
- MB Y75 removing 512kb files bug fixed.
- Mercedes B EGR Removing solution added
- Mercedes DCM3.2 Micro solution added.
- Mercedes DCM3.5 P0400 remove added
- Mercedes Delphi DCM3.5 solution added
- Mercedes Delphi DCM3.5 solution added new DTCs for removing
- Mercedes EDC15C7 both solution added P1403 removing.
- Mercedes EDC16 M55 fix section improved
- Mercedes EDC16C02 solution more improved
- Mercedes EDC16C31 - EDC16CP31 solution has been improved
- Mercedes EDC16C31 lmb item now sum to in 1 one and improved.
- Mercedes EDC16C31 customer DTC improved, added new signs
- Mercedes EDC16C31 New models improved.
- Mercedes EDC16C31 New section added some reported DTCs for other models
- Mercedes EDC17C10 added
- Mercedes EDC17CP10 more signs added.
- Mercedes EDC17CP10 new sign added
- Mercedes EDC17CP10 solution improved.
- Mercedes EDC17CP11 new DTCs added
- Mercedes Y75 solution new signs added
- Mitsubishi Denso more DTCs added

- Mitsubishi EDC16C31 solution has been added
- Mitsubishi EDC16U31 added
- Mitsubishi Pajero Denso EGR Removing added
- Nissan Denso 1 mb and 1.5 mb file 2 solution added
- Nissan Denso EGR removing has been improved
- Nissan EDC16C3 added
- Nissan EDC16C36 + DTCs added
- Nissan EDC16CP42 EGR maps fixed
- Nissan SID305 2nd P1525 DTC check - remove added
- Opel Antara solution added in EDC16C39 Generic item
- Opel Delco Hybrid Astra Type added
- Opel Denso Astra models DTCs removing added
- Opel Denso solution added.
- Opel Denso solution more improved
- Opel Denso solution more improved
- Opel Denso Z17DTH type ECU solution has been added
- Opel EDC16C39 DTC P2279 removing added
- Opel EDC16C39 improved for Antara model.
- Opel EDC16C39 revized switch solution
- Opel EDC16C9 improved
- Opel EDC16C9 new signs added
- Opel EDC16C9 Signum model solution added
- Opel EDC16C9 Type2 added new signs
- Opel EDC16C9.23 solution new signs added
- Opel EDC17C18 Added
- Opel EDC17C46 Added
- Opel EDC15C2 bug fixed
- Opel Magneti Marelli 6f3 ECU DTC table supporting improved to all models.
- Opel PSG16 sign problem has been fixed
- Opel PSG16 solution added
- Opel Signum3.0 Denso EGR solustion added
- Opel Vectra 2.0 DTI EDC15C0 Old Model
- Opel Vivaro EDC16C36 solusion revized
- Opel Z13DTJ solution improved.
- Packet file, encrpyted file detection added.
- PCR2.1 Caddy type Egr Hysteresis map bug fixed
- PCR2.1 Generic item added new soft version Golf6 file supports
- PCR2.1 Generic solution important bug has been fixed
- PCR2.1 Generic solution improved for Golf6 models)
- PCR2.1 generic solution maximum improved
- PCR2.1 generic tuned file EGR remove problem has been fixed
- PCR2.1 solution 8th map added new sign.
- PCR21 Type3 signs improved to all types file
- Peugeot - Renault Delphi DCM3.4 EGR removing has been added
- Peugeot EDC15C2 different type signs added
- Peugeot EDC16C34 Typel P2143 DTC added
- Peugeot EDC16C34 Typel Revized
- Peugeot EDC16CP39 P1445 DTC disable added
- Peugeot SID803 MPC solution test byte removed
- Peugeot Typel solution P0405 DTC calculation added.
- Peugeot EDC16c-7 EGR solution added.
- Peugeot - Citroen EDC17CP10 Addive Pump removing added
- Peugeot SID801 solution has been added.
- Polish language update to more good
- Portuguese, Rumanian and Dutch languages some problems has been fixed.
- PPD1.x EGROFF solution added
- PPD1.x improved for Passat models.
- Program security improved. Internal traps number now up to 289.
- PSA SID803 MPC solution revized
- Range Rover EDC17CP11 added, DTC's improved
- Range Rover EDC17CP11 TDV6 model signs added
- Range Rover SID204 DTC structures re-assembly for some models
- Renault - Nissan EDC16CP33 added
- Renault 1.5 CDI solustion added

- Renault Delphi DCM3.4 solution added
- Renault Delphi DDCR P1014 + EGR Map added
- Renault EDC15C3 new signs added for EGR switches.
- Renault EDC16C3-21.9 more DTCs removing added
- Renault EDC16C3-9.21 added new solution for different type ECUs.
- Renault EDC16C3-9.21 EGR map fill values has been set to 00
- Renault EDC16C3-9.21 revized, added full DTC's.
- Renault EDC16C36 DF647 DTC removing added
- Renault EDC16C36 re-improved for Injector detection problem
- Renault EDC16c36 solution fixed, revized.
- Renault EDC16C41 (Mascot) solution has been added
- Renault EDC16C9 Full DTC removing added
- Renault EDC16CP33 added
- Renault EDC16CP33 improved, optimized
- Renault SID305 solution added
- RenaultEDC16C36 extra points added and improved
- Saab EDC16C39 Remap item added P0400 DTC removing.
- Saab EDC16C39 solution has been improved
- SID803 MPC solution second P0409 DTC removing added
- Siemens PPDv1.x Hotstart Fix added
- Skoda EDC17C46 added
- Skoda EDC17C46 added
- Skoda EDC17U01 solution added
- Smart EDC15 solution has been added
- Smart EDC16C31 added.
- Smart EDC16C31 Solution added
- Suzuki EDC16C8 Solution2 bug has been fixed
- Suzuki Vitara EDC16C3 revized
- Swedish Language has been added
- Toyota Denso Hilux solution has been added
- Toyota Denso solution added
- Toyota EDC16C31 solution has been improved
- Treeview font size decreised 2 punto
- Update period calculation bug has been fixed.
- Vauxhall - Opel EDC17C59 solution improved
- Volvo SID206 custom DTC removing support added.
- Volvo SID803 MPC added
- VAG EDC16U1 custom DTC calculation bug fixed.
- VW - Audi EDC16U31 Typ1 solution improved with new signs
- VW - Audi EDC17C46 solution improved for different Audi models.
- VW - Seat EDC16U34 Hotstart fix has been added
- VW EDC16C34-4 Crafter solution added some new reported DTCs
- VW EDC16U1 both DTC P401 added
- VW EDC16U1 solution has been revised
- VW EDC16U34 Caddy models P0407 removing added
- VW EDC16U34 improved for Caddy models
- VW EDC17C46 solution improved.
- VW EDC17CP04 Solution added
- VW EDC17CP52 menu bug fixed
- VW ME7.5.10 ECUs EGR removing solution added (P0401 disabled)
- When making Flap removing, was showing DPF removing message. All messages are fixed.

Alfa : EDC16C39, EDC15C7,EDC16C8, EDC16C39 Generic
Audi : EDC16U1, EDC16U31 Typ1 and Typ2,EDC15VM+,
EDC17CP14,PCR2.1,EDC16CP34,EDC17C46
BMW : EDC16C31 Typ1 and Type2, EDC16CP35, EDC16CP35, EDC17CP02
Chrysler : EDC16CP31
Citroen : EDC16C39, EDC16C34, SID803A, EDC15C3, SID803, EDC17C10,
EDC16CP39
Dodge : EDC16U31-4 Typ1 and Type2
Fiat : EDC15C7, EDC16C39 Typ1 and Type2, EDC16C8,Marelli MJ 70-75-
90CV,SID803A, Simos, Doblo Type

Ford : EDC16C3-9, EDC16C34, Visteon, EDC16C9 Cmax Type, SID206,
 SID804
 Honda : EDC16C31
 Hyundai : EDC15C7
 Lancia : EDC15C7, EDC16C39, EDC16C8, Marelli MJ 70-75-90CV, SID803A
 Land Rover : EDC16CP39, SID204
 Iveco : EDC16C39
 Isuzu : Transtron (DMax Type)
 Nissan : EDC16CP33, EDC16C3
 Mazda : EDC16C34-2
 Mercedes : EDC16C31 (1 and 2 mb types), EDC15C6 (Switch and Remap),
 EDC16C31 Type2, EDC16CP31
 M55 Fixer, EDC17CP10, EDC16CP36

 Mini Cooper : EDC16C35
 Mitsubishi : EDC16U31
 Opel & Vauxhall : EDC16C3, EDC16C39, EDC16C36, Marelli MJ 70-75-90CV, Z19DTH,
 Denso, EDC17C18, EDC17C46, Delco
 Peugeot : EDC16C34, EDC15C2, SID803A, EDC15C3, SID803, EDC16CP33,
 EDC16CP39
 Range Rover : EDC17CP11
 Renault : EDC16C3, EDC15C2, EDC16C3 Type2, EDC16CP36, Delphi DDCR
 Saab : EDC16C9
 Seat : EDC16U1, EDC17CP14, PCR2.1, PPD1.x
 Skoda : EDC15VM+, EDC16U1, PCR2.1, PPD1.x, EDC17C46
 Suzuki : Marelli MJ 70-75-90CV, EDC16C3
 Volvo : EDC16, SID803, EDC17CP22
 VW : EDC16U1, EDC17CP14, EDC17CP20, EDC16, PCR2.1, EDC16U34,
 EDC16CP34-4, PPD1.x, VW EDC17CP04

 Hotstart

EDC16C31, EDC16U1, EDC15, Siemens PPDv1.1 - v1.2

Special EDC15C2 - C3 switch finder

 Professional Lambda Remover v2017.03

- Audi ME7.5
- Audi ME7.5 support for other models has been improved
- Audi MED17.1 P0420 CAT removing has been added
- Audi Simos84 solution added
- BMW MSD80 CAT removed solution added
- Ford Focus ME9.0C Lambda + O2 solution added
- Ford ME9.0c P0038 DTC removing added
- Ford ME9.0c P0038 DTC removing added
- GUI improved and languages added
- Honda ME7.9.2 Lambda removing has been added
- Maserati CAT OFF solution added
- ME7.5 Lambda solution added
- MED 7.5.11 P1070 removing added
- Mercedes ME2.8 solution improved for different MB models.
- Nox MED9.5.10 improved
- Nox MED9.5.10 improved
- Nox, O2 and CAT solutions added.
- Octavia Simos 7.1A CAT - O2 removing added
- Opel Corsa ME7.6.1 O2 solution added
- Peugeot IAW48P O2 - CAT removing solution added
- Program coded from starting, more fast and solutions more improved
- PSA ME7.4.4 has been improved.
- Saab Tronic 7 and 8 CAT removing added

- Seat Marelli 4Mx CAT removing has been added
- Seat Marelli 4Mx CAT removing has been added
- Skoda MED9.5.10
- Smart ME7.7.0 solution added
- Solutions included automatic DTC calculations for 0 error.
- Suzuki Swift Denso CAT removing added
- Swedish Language has been added
- Toyota ME7.9.2 CAT removing added
- Toyota ME7.9.52 signs added
- Toyota ME7.9.52 signs added
- Volvo Turbo Series M4.1.1 Lambda - CAT remove solution added
- Volvo Turbo Series M4.1.1 Lambda - CAT remove solution added
- VW Bettel Simos33 Lambda solution added
- VW MED9.1 CAT improved
- VW MED9.1 CAT improved
- VW MED9.1 O2 - CAT removing added

Alfa	: ME7.3.1, ME7.3H4, ME7.9.10, MED9.5.10
Audi	: ME7.1, MED9.1.1, MED9.5.10
BMW	: ME9
Chrysler	: ME2.8
Citroen	: ME7.4.4, ME7.4.5, ME7.4.6
Dodge	: ME2.8
Fiat	: ME7.3H4, ME7.9.10
Ford	: ME7.9
Jeep	: ME2.8
Lancia	: ME7.3H4
Mercedes	: ME2.8, ME2.8.1
Opel	: ME1.5.5, ME7.6.2
Peugout	: ME7.4.4, ME7.4.5, ME7.4.6
Seat	: ME7.7.10
Skoda	: ME7.1
Volvo	: ME7.0 XEP
VW	: ME7.1, ME7.5.10, MED9.1
BMW ME9	

** All Car brands are copyright, All ECU names and brands are copyrights **